

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthome Street San Francisco, CA 94105-3901

MAR 1 8 2004

Certified Mail No. 7001 0320 0002 4540 8653 Certified Receipt Requested

In reply, refer to WST-3

NOTICE OF VIOLATION

Diana Crane Quality Manager Associated Plating Co. 9636 Ann St. Santa Fe Springs, CA 90670

Dear Ms. Crane:

On November 17, 2003, a hazardous waste investigation was conducted by representatives of the United States Environmental Protection Agency ("EPA"), accompanied by a representative from the Santa Fe Springs Fire Department Environmental Protection Division, at Associated Plating Co. located at 9636 Ann St., Santa Fe Springs, CA 90670, EPA Identification Number CAD043079110. During the course of this investigation, information was gathered in accordance with Section 3007 of the Resource Conservation and Recovery Act ("RCRA"), as amended [42 U.S.C. 6927]. A copy of the investigation report is enclosed for your information and response. The report describes conditions at the facility at the time of the investigation, and identifies areas of noncompliance with the California authorized program under RCRA Subtitle C. Any omissions in the report shall not be construed as a determination of compliance with all applicable regulations.

Pursuant to Section 3008 of RCRA [42 U.S.C. 6928] you are required to perform the following tasks:

- I) Perform a waste determination on the liquid underneath the grating in the nickel stripping area. If this liquid has already been containerized and transported offsite for disposal, please provide EPA with a copy of the manifest (or if this manifest was already included in your December 22, 2003 letter to EPA, please indicate the manifest number and date);
- II) Create and implement a weekly inspection checklist to be used for all waste storage areas and satellite accumulation areas. This checklist should include at a minimum:
 - that all hazardous waste containers stored on the facility premises meet all labeling requirements;
 - that no more than 55 gallons of a particular wastestream be stored at any satellite

accumulation area;

- that all hazardous waste containers be closed (including with locking rings) when waste is not being added or removed from the containers;
- that there be proper access to all hazardous waste containers;
- that all hazardous waste containers be in good condition;
- that no hazardous waste be stored beyond the permitted storage time;

Please send a copy of this checklist to EPA.

- III) Install an internal alarm for the hazardous waste storage area, as is required under CCR Title 22 §66265.34(a). Please provide EPA photographic documentation of this;
- IV) Please provide a complete contingency plan that includes a list of all emergency equipment, along with each emergency device's location and a brief description of the device, as required under CCR Title 22 §66265.52(e)

By copy of this letter, EPA is providing the State of California with notice of the referenced violations of Subtitle C of RCRA. EPA is also providing the State with notice that EPA may take appropriate enforcement action. The State of California may notify EPA of its intent to assume or decline responsibility to take such action to resolve the referenced violations. EPA reserves the right to take further enforcement action as it deems appropriate.

EPA routinely provides copies of investigation reports to state agencies, and upon request, to the public. Such releases are handled according to the Freedom of Information Act regulations (40 CFR Part 2). If you believe this report contains privileged or confidential information, you may make a claim within fourteen (14) calendar days from the date of receipt of this letter. EPA will construe your failure to furnish a timely claim as a waiver of the confidentiality claim.

This request for information is not subject to review by the Office of Management and Budget ("OMB") under the Paperwork Reduction Act because it is not an "information collection request" within the meaning of 44 U.S.C. §§3502(3), 3507, 3512, and 3518(c)(1). See, also, 5 C.F.R. §§ 1320.3(c), 1320.4, and 1320.6(a). Furthermore, it is exempt from OMB review under the Paperwork Reduction Act because it is directed to fewer than ten persons. 44 U.S.C. §3502(4), (11); 5 C.F.R. §§ 1320.4 and 1320.6(a).

Your response to this request must be made by letter, signed by a duly authorized official, and submitted to EPA within thirty (30) calendar days from the date of receipt of this letter. Please address the submittal to:

Clint Seiter
Mailcode: WST-3
RCRA Enforcement Office
U.S. Environmental Protection Agency,
75 Hawthorne Street

San Francisco, CA 94105

If you have questions related to technical aspects of the investigation report or this letter, please contact Clint Seiter at (415) 972-3298.

oren Henning, Manager

RCRA Enforcement Office

Enclosure

cc w/o enclosure: Steve Lavinger, DTSC

Richard Kallman, Santa Fe Springs Fire Department



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY REGION IX 75 Hawthorne Street

75 Hawthorne Street San Francisco, CA 94105

WASTE MANAGEMENT DIVISION

RCRA ENFORCEMENT OFFICE

Purpose:

RCRA Compliance Evaluation Inspection

Facility:

Associated Plating Co.

9636 Ann St.

Santa Fe Springs, CA 90670

EPA ID Number:

CAD043079110

Date of Inspection:

November 17, 2003

EPA Representatives:

Clint Seiter

Environmental Protection Specialist

(415) 972-3298

Aubrey Baure

Environmental Scientist

(415) 972-3294

Santa Fe Springs

Richard Kallman

Fire Department:

Environmental Protection Specialist

(562) 906-3810

Facility Representative:

Diana Crane, Quality Manager

(562) 946-5525

Report Prepared By:

Clint Seiter

Report Date:

January 27, 2004

BACKGROUND

Facility Description

Associated Plating Company ("Associated Plating" or "the Facility") specializes in nickel metal plating, but also performs plating operations with copper, tin, tin-lead alloys, gold and silver. No cadmium or chromium plating is performed by the Facility. The Facility is located at 936 Ann St., Santa Fe Springs, CA, and has occupied its current location since the mid-1970s. The Facility currently employs 52 workers. Per the manifest database of the California Department of Toxic Substance Control (DTSC), Associated Plating generates sufficient quantities of RCRA hazardous waste to qualify as a Large Quantity Generator.

Per Associated Plating's 2001 Biennial Report, the Facility generated the following hazardous wastestreams:

- Rinse water from electroplating operations containing traces of lead (D008)
- Wastewater treatment sludge from plating operations containing metal hydroxide (F006)
- Rinse water from electroplating operations containing traces of cyanides (D003)
- Spent stripping solutions containing copper and nickel (D002)
- Spent tetrachloroethylene used for degreasing parts (F001)
- Spent gold stripping solution containing cyanide (F009)
- Spent silver and gold plating solutions containing cyanide (F007)
- Waste paint material (D001)

Associated Plating submitted an initial Notification of Hazardous Waste Activity on 8-15-80 identifying itself as a generator of F001, F006, F007, F008, and F009 hazardous waste (Attachment 2) and was assigned an EPA identification number of CAD043079110. The Facility renotified on 11-15-99 to inform EPA of a change of ownership, this time identifying itself as a large quantity generator of the following RCRA hazardous waste: D002, D003, F001, F006, F008 and F009 (Attachment 3).

Enforcement History

The EPA inspection database indicates that Associated Plating was previously inspected on 11-5-1992 by the California Department of Toxic Substance Control (DTSC) where pre-transport related generator violations were noted and subsequently corrected. The Facility was last inspected by the Santa Fe Springs Fire Department Environmental Protection Division on 2-7-02 (Attachment 4), where the following violations were noted:

- Labeling violations (no labels, unreadable labels, incomplete labeling);
- Storage together of incompatible wastes;
- Storage of hazardous wastes for over 90 days;
- Releases of hazardous wastes;
- Incomplete training records.

The Facility returned to compliance on 2-26-02.

Plating Process Description

Associated Plating operates four plating lines, as follows:

Line 1: nickel, alkaline tin and acid tin plating;

Line 2: tin, tin-lead, nickel plating (for parts requiring solderability);

Line 3: mickel plating barrel line (for large volumes of small parts (nuts, bolts, etc.). Parts to be plated are placed in a barrel with a mesh screen, and the barrel is rotated in the plating solution);

Line 4: Electroless nickel plating (used on aluminum substrates).

Plating operations differ from line to line, but the basic operation is as follows:

Tank 1: Alkaline soak (removes oils and dirt from substrate);

Tank 2: Electro-cleaner. Part is placed in an alkaline solution through which an electric current is run. Tanks vary in size, according to which line is used, from 70 gallons to 1300 gallons. Solution pH ranges from 12 to 13. Tank is changed every 3 to 6 months. Spent solution is processed through the Facility's wastewater treatment system;

Tank 3: Rinse tank;

Tank 4: Acid bath: 30% hydrochloric acid solution. Prepares substrate for the plating process. Bath is changed approximately every 2 months. Spent acid is neutralized on site, metals are precipitated out, and the remaining solution is processed through the wastewater treatment system;

Tank 5: Nickel strike tank (used in mickel plating lines). Provides a more receptive substrate for the subsequent nickel plating. Solution consists of nickel chloride and hydrochloride acid, with an electric current passed through it;

Tank 6: Rinse tank;

Tank 7: Nickel plating tank (400 gallons): Electroplating operation using nickel sulfamate;

For parts requiring only a nickel plating, the process ends here. For a part that is to be goldplated (with a nickel substrate) the process continues as follows:

Tank 8 Gold strike. Solution of potassium gold cyanide with an inert anode of titanium mesh with a platinum coating. Solution is used indefinitely without changing, but with occasional replenishing;

Tank 9 Gold plating tank. Solution of potassium gold cyanide, with an inert cathode.

Electric current is passed through the solution and the part acts as a cathode, with the gold deposited on it;

Tank 10 Gold drag out. A static tank. Current passing through the solution deposits trace amounts of gold on a plating cell for gold recovery.

The Facility also has a small laboratory in which the plating solutions are analyzed on a weekly basis. Both wet analysis and atomic adsorption analysis are performed in the lab. Solutions analyzed are returned to the baths once the analysis has been completed.

INVESTIGATION

The purpose of the investigation was to determine Associated Plating's compliance with applicable federal environmental statutes and regulations, and in particular, the Resource Conservation and Recovery Act (RCRA), as amended, the regulations provided in the Code of Federal Regulations (CFR), Chapter 40, Parts 261-265, 268 and 279, and the California Code of Regulations (CCR), Title 22, Division 4.5 and the California Health and Safety Code, Division 20, Chapter 6.5. On November 17, 2003, Clint Seiter and Aubrey Baure, representing the U.S. Environmental Protection Agency (EPA), and accompanied by Richard Kallman, representing the Santa Fe Springs Fire Department, conducted an unannounced site investigation at Associated Plating, Santa Fe Springs, CA (EPA ID# CAD043079110). Upon providing introductions and credentials, the inspectors contacted Ms. Diana Crane, the Facility's quality manager. The inspectors explained that this was a routine inspection to determine whether or not the Facility was in compliance with federal and state regulations concerning the proper management of RCRA and non-RCRA hazardous wastes. The inspection would consist of a walkthrough of the Facility, focusing on those areas where hazardous wastes were bandled or stored, with photos taken, followed by a record review and a post-inspection outbriefing. In the course of the pre-walkthrough briefing, the inspectors provided Ms. Crane with a copy of the Small Business Regulatory Enforcement Fairness Act (SBREFA) Information Sheet.

Walk-Through Inspection (see Attachment 5 for a Facility layout)

-Plating Line 5

The inspectors noted the following:

Four open, 15-gallon carboys containing spent nickel filters (a non-RCRA, California only hazardous waste) (Attachment 1, Photo 1). The carboys were unlabeled. In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), these filters were identified as a non-RCRA, California-only hazardous waste.

- Plating Line 1

The inspectors noted the following:

- One open, unlabeled, green 5-gallon bucket, 3/4 filled with a black liquid (Attachment 1, Photo 2). The Facility representative was unable to identify the bucket's contents at the time of the inspection. In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "chromate rinse used in processing" returned to the rinse system;
- One open, unlabeled 5-gallon bucket, 1/8 full of unidentified black liquid (Attachment 1, Photo 3). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "chromate rinse used in processing" returned to the rinse system;

- One open, unlabeled 15-gallon carboy, 1/4 full with a clear liquid (Attachment 1, Photo
 4). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "chromate rinse used in processing" returned to the rinse system;
- Two open, unlabeled 30-gallon containers of a clear liquid (Attachment 1, Photo 5). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "chromate rinse used in processing" returned to the rinse system;
- One 10-gallon container with a dark yellow liquid (Attachment 1, Photo 5) identified as "chromate rinse used in processing" returned to the rinse system;
- One unlabeled 55-gallon drum. In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "copper solution removed from tank during pump repair - returned to tank";
- One 55-gallon, closed drum, labeled with the words: "chromium etch, cleaners line 4, tank 4, 6/11/03". In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this was identified as "chromate rinse used in processing" that was returned to the rinse system;
- One 55-gallon, unlabeled, closed drum. In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "chromate solution that had been decanted from a process tank - reused";

- Between Lines 1 and 3

The inspectors noted the following:

- One open, unlabeled 55-gallon drum, 1/8 full (Attachment 1, Photo 6). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "rinse water from chromate processing";
- Two unlabeled 15-gallon carboys (Attachment 1, Photo 7). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "spent sulfuric acid solution used for hourly cleaning of the electro coagulation unit". Per this letter, this was identified as a D002 hazardous waste, with an accumulation start date of 10-17-03. The waste was transported offsite for disposal on 12-16-03;
- One open, unlabeled 55-gallon drum, 3/4 full of a greenish liquid (Attachment 1, Photo 8). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "in-process sulfuric acid used for hourly cleaning of the electro coagulation unit";
- Three open, unlabeled 15-gallon containers, approximately 1/4 full (Attachment 1, Photo 9). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "evaporated chromate rinses. Returned to process tank to recover chemistry."
- Four, closed 55-gallon drums (Attachment 1, Photo 10):
 - 1st drum labeled: "line 3, copper flow, 3-13-03";
 - 2nd drum labeled: "line 3, copper flow, 3-13-03";
 - 3rd drum labeled: "copper rinse, 3-13-03";

- 4th drum labeled: "copper rinse, 3-13-03";

In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), drums' contents were identified as "water collected from routine berm cleaning" which was subsequently treated onsite via the Facility's wastewater treatment system;

Two open black, 15-gallon carboys, 1 filled with a white solid, one filled with a white solid and 3 inches of liquid (Attachment 1, Photo 11). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), solids identified as "solids from copper tank maintenance", with an F008 RCRA hazardous waste code. Per the letter the waste had been generated on 9-12-03 and had yet to be disposed of.

- Between Lines 2 and 4

The inspectors noted the following:

- Two tubes (one yellow, one black), filled with a milky fluid (Attachment 1, Photo 12). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "in-process solution used for tin stripping";
- One open, 5-gallon red bucket with a "Hazardous Waste" label, 1/8 full of clear liquid with a yellow deposit (Attachment 1, Photo 13). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), this liquid was identified as "dehydrated rinses from chromate treatment", an F006 RCRA hazardous waste. Per the letter, the waste's accumulation start date was 9-12-03 and it had yet to be disposed of;

- Blasting Booth

Per the Facility representative, a mixture of silicon aluminum oxide and pumice is used as a blasting medium. Spent blasting medium is disposed of with the filter cake generated from the Facility's waste water treatment system (Attachment 1, Photo 14).

- Electroless nickel pumping room

Per the Facility representative, the pipes which convey the electroless nickel plating solution expand due to the heat generated in the Facility, and leak solution. There was an open catch basin underneath the pipes to collect any solution that leaks from the pipes. There was also an open, unlabeled bucket containing discarded steel wool plated with nickel (with spent electroless nickel plating solution, the nickel is plated out onto steel wool before the solution is processed out through the Facility's wastewater treatment system). This nickel plated steel wool is a non-RCRA, California only hazardous waste.

- Line 3

The inspectors noted the following (Attachment 1, Photo 15):

- One open, unlabeled, blue 5-gallon bucket;
- One open, unlabeled, white 5-gallon bucket containing an unidentified brown liquid;
- One open, unlabeled, white 2-gallon bucket containing an unidentified brown liquid;
- One open, unlabeled, red 5-gallon bucket containing an unidentified black liquid;

The Facility's letter to EPA dated December 22, 2003 (Attachment 7), stated that these buckets contained "alkaline cleaner from tank skimming". Per the Facility letter, this was a D002 RCRA hazardous waste generated on 11-17-03 and treated on site on 11-19-03.

- One open, unlabeled, blue, 15-gallon drum, 3/4 filled with black liquid. The Facility's letter to EPA dated December 22, 2003 (Attachment 7), stated that this drum contained "cleaner sludge from tank maintenance" (Attachment 1, Photo 16) that was returned to the process tank.

- Waste Storage Yard (Stripping Area)

Per the Facility representative, occasionally errors occur in the nickel plating process, and the part has to be stripped of the nickel hy immersion in a hydrochloric acid solution and replated. Spent stripping solution is stored in this area for neutralization.

The inspectors noted 21 55-gallon drums of spent electroless nickel plating solution (a non-RCRA hazardous waste) in the stripping area. None of the drums were labeled (Attachment 1, Photo 17). The immediate stripping room consisted of a 15'x10' bermed area covered with a grate (Attachment 1, Photo 18). The inspectors noted that the area beneath the grating was filled with liquid. A piece of litmus paper was applied to the liquid, and the inspectors determined that the liquid had a pH of approximately 1, which would qualify the liquid as a D002 RCRA corrosive hazardous waste.

-Waste Storage Yard (Main Area)

The main waste storage yard was a large, enclosed exterior area filled with 55-gallon drums, none of them labeled except for a number written on the sides or tops (Attachment 1, Photos 19-21). The Facility representative informed the inspectors that numbers identified the drums in a central tracking system database. Per the representative, many of the drums contained hazardous wastes (either RCRA or non-RCRA, California only), some contained non-hazardous waste, and some contained product. The representative said that the database indicated there were 193 drums in the yard. This conformed to the rough estimate that the inspectors made (a more accurate count was difficult hecause drums were dispersed in various parts of the yard). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), the Facility provided an inventory of the drums, identifying their contents, their waste codes (if applicable) and their accumulation start dates, when possible. Based upon this inventory, the following table summarizes the RCRA hazardous waste containers stored in the waste storage yard at the time of the inspection:

TABLE 1							
Drum #	Waste name	Waste code	Accumulation start date	Disposal date	# days		
1	Nickel strip	D002	8-7-03	12-12-03	128		
2	Nickel strip	D002	8-21-03	12-12-03	114		
5	Nickel strip	D002	8-7-03	12-12-03	128		
6	Nickel strip	D002	8-21-03	12-12-03	114		
7	Nickel strip	D002	9-4-03	12-12-03	100		
9	Unknown acidic	D002	unknown*	12-10-03	?		
25	Unknown acidic	D002	10-8-03	12-10-03	64		
26	Unknown acidic	D002	10-9-03	12-10-03	63		
27	Unknown acidic	D002	10-11-03	12-10-03	61		
30	Unknown alkaline	D002	unknown*	12-5-03	?		
35	Nickel strip	D002	9-11-03	12-12-03	93		
36	Nickel strip	D002	9-25-03	12-12-03	79		
40	Silver strip	D002	unknown*	still at site	?		
41	Silver strip	D002	unknown*	still at site	?		
42	Nickel strip	D002	9-18-03	12-12-03	77		
47	Nickel strip	D002	10-16-03	12-12-03	58		
49	Nickel strip	D002	7-24-03	12-12-03	142		
52	Unknown acidic	D002	10-10-03	12-5-03	57		
55	Liquid from filters	F006	10-3-03	10-17-03	14		
60	Unknown acidic	D002	10-15-03	12-10-03	57		
61	Unknown acidic	D002	9-22-03	12-10-03	80		
62	Unknown acidic	D002	9-8-03	12-10-03	94		
64	Unknown acidic	D002	unknown*	12-10-03	?		

Drum #	Waste name	Waste code	Accumulation start date	Disposal date	# days
66	Unknown acidic	D002	unknown*	12-10-03	?
67	Unknown acidic	D002	8-9-03	12-4-03	118
68	Unknown acidic	D002	9-9-03	12-10-03	93
81	Unknown acidic	D002	10-22-03	12-10-03	50
84	Unknown acidic	D002	10-31-03	12-10-03	41
85	Unknown acidic	D002	9-18-03	12-10-03	40
86	Unknown acidic	D002	unknown*	12-10-03	?
102	Unknown acidic	D002	unknown*	11-17-03	?
103	Unknown acidic	D002	unknown*	12-5-03	?
104	Unknown acidic	D002	unknown*	12-5-03	?
105	Unknown acidic	D002	10-28-03	12-5-03	39
106	Unknown acidic	D002	unknown*	12-10-03	?
107	Unknown acidic	D002	unknown*	12-5-03	?
176	Nickel strip	D002	11-6-03	12-12-03	37

^{*} In a post-inspection telephone conversation, the Facility representative informed the inspector that it was impossible to ascertain the accumulation start dates of these containers, many of whom were stored on the Facility premises when she first began her employment at the Facility in July, 2003.

During the inspection the inspectors informed the Facility representative that all drums of RCRA and non-RCRA hazardous wastes had to conform to the regulatory labeling requirements as described in Title 22 of the California Code of Regulations (CCR). Because the drums were so tightly packed together, approximately half of them lacked access, as is required under CCR Title 22 §66265.35.

The inspectors also noted the following:

six supersacs (one of which was unlabeled) that were identified by the Facility representative as containing F006 filter cake (Attachment 1, Photo 22) (In the Facility's 12-22-03 letter to EPA, the Facility included a manifest dated 9-12-03 for 2 cubic yard containers of F006 filter cake. This would substantiate the Facility's claim that the unlabeled supersac of filter cake noted during the 11-17-03 inspection had been there for less than 90 days);

- one 1200-gallon open tank, labeled only "treated sludge" (Attachment 1, Photos 23 and 24). There was a clear liquid in the tank, with approximately 2" of freeboard. In the Facility's December 22, 2003 letter, the Facility identified the tank's contents as "spent cleaner solution", with a D002 RCRA hazardous waste code. The Facility representative was unable to provide an accumulation start date.
- two unlabeled 2500 gallon tanks, filled, according to the Facility representative, with "cadmium treatment coagulate" (Attachment 1, Photo 25), which, per the Facility representative, is part of the closed loop rinse system.

The inspector also noted that there was no immediate access to an internal alarm in the waste storage area, as required under CCR Title 22 §66265.34(a).

- Analytical Lab

The inspectors noted a 1-gallon container with a hazardous waste label that was not filled out, except for the words "Sulfuric Acid" (Attachment 1, Photo 26). In the Facility's letter to EPA dated December 22, 2003 (Attachment 7), the Facility identified this as a product used in lab analysis, not a waste.

The inspectors also noted two open, unlabeled 5-gallon buckets of plating solutions slated for lah analysis, identified as acidic and alkaline titration solutions from lab analysis. Per the facility representative, these solutions are poured back into the tanks after the testing has been completed.

Record Review

Manifests: the inspectors noted no manifest discrepancies.

Biennial Report, Contingency Plan, Training Records: the Facility representative was not able to readily locate these documents. The inspectors requested that, once located, she mail them to the EPA for review. Training records and manifests for 2004, 2003 and 2002 were submitted to EPA in the Facility's December 22, 2003 letter (Attachment 7). No violations were noted upon review of these documents.

The facility's contingency plan was submitted on January 23, 2004. A review of this document revealed that the contingency plan conformed to the regulatory requirements as described in CCR Title 22 §66265.52 except that it lacked a list of all emergency equipment, including the location and hrief description of each device.

Post Inspection

On December 2, 2003, EPA mailed to the Facility a 3007(a) Request For Information letter, requesting the following (Attachment 6):

- In the print-outs provided of 186 waste containers in the waste storage yard:
 - the waste codes (RCRA and/or non-RCRA, California only) for the contents of each container;
 - the accumulation start date (i.e., when the container was first filled with the waste) with any available documentation, for each container.
- Copies of all hazardous waste manifests for the years 2001, 2002 and 2003;
- Training records as described in Title 22 of the California Code of Regulations §66265.16(d)(1)-(4), that is:
 - the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job;
 - a written job description for each position listed;
 - a written description of the type and amount of both introductory and continuing training that will be given to each person listed above;
 - records that document that the training or job experience required have been completed.
- Waste determinations of the various unlabeled containers noted along the plating lines during the 11-17-04 inspection (as detailed above in this report).

The Facility responded with a letter to EPA dated December 22, 2003 (Attachment 7), which included the information referenced in the report above.

On January 23, 2004, the facility submitted a copy of its contingency plan to EPA as described above.

On February 24, 2004 a follow-up Case Development Inspection was conducted on Associated Plating. The inspection revealed that the facility's housekeeping had substantially improved. There were no longer any open, unlaheled waste containers between the plating lines, and the containers previously noted in the waste storage area during the first inspection had been removed.

POTENTIAL RCRA VIOLATIONS

Failure to make a hazardous waste determination

Title 22 §66262.11 (40 CFR §262.11)

Satellite Accumulation Area Labeling Requirements

Title 22 §66262.34(e)(1)(C); Title 22 §66262.34(e)(1)(E) (40 CFR §262.34(c)) A person who generates a waste shall determine if that waste is hazardous.

The facility did not make hazardous waste determinations for the wastewater beneath the grate in the stripping room.

A generator may accumulate as much as 55 gallons of hazardous waste at or near any point of generation if each container used for onsite accumulation is labeled with the words "Hazardous Waste" and with the following information:

- (A) the initial date of waste accumulation is clearly marked and visible for inspection on each container used for accumulation of hazardous waste;
- (B) composition and physical state of the waste;
- (C) the particular hazardous properties of the waste;
- (D) the name and address of the person producing the waste.

The following satellite accumulation area hazardous waste containers did not have this labeling information:

- 2 unlabeled 15-gallon carboys of spent sulfuric acid (D002) between Lines 1 and 3;
- 2 15-gallon carboys of F008 hazardous waste between Lines 1 and 3;
- 1 open, 5-gallon red hucket, 1/8 full of F006 hazardous waste between Lines 2 and 4;

90-Day Hazardous Waste Storage Area Labeling Requirements

Title 22 §66262.34(a)(3) and (f) (40 CFR §262.34(a)(3))

Open Containers

Title 22 §66265.173(a) (Article 9) (40 CFR §265.173(a))

- 4 open buckets of alkaline cleaner from tank skimming (D002) by Line 3;

Each container used for onsite accumulation of hazardous waste shall be labeled or marked clearly with the words "Hazardous Waste". Additionally, all containers shall be labeled with the following information:

- the initial date of waste accumulation is clearly marked and visible for inspection on each container used for accumulation of hazardous waste;
- composition and physical state of the waste;
- the particular hazardous properties of the waste;
- the name and address of the person producing the waste.

The Facility did not provide this labeling information for the following waste containers in the 90-day storage yard:

- All the containers listed in the above TABLE 1;
 - 1 supersac of F006 filter cake;
- 1 1200-gallon tank of D002 spent cleaner solution.

Title 22 §66262.34(e)(10) states that a generator may accumulate hazardous waste on-site without a permit provided that the generator complies with the applicable requirements of articles 9 of chapter 15. Title 22 §66265.173(a) (Article 9) states that a container holding hazardous waste must always be closed during storage, except when it is necessary to add or remove waste.

The following hazardous waste containers were open at the time of the inspection:

- 2 open 15-gallon carboys of F008 RCRA hazardous waste between Lines 1 and 3;
- 1 open, 5-gallon red bucket, 1/8 full of F006 hazardous waste between Lines 2 and 4:
- 4 open buckets of alkaline cleaner from tank skimming (D002) by Line 3;

A (large quantity) generator may accumulate hazardous waste on-site for 90 days or less without a permit.

A minimum of 10 55-gallon drums of D002 nickel stripping solution or unknown acidic solution were stored on the facility premises for over 90 days.

Per Title 22 §66262.34(a)(4), a generator may accumulate hazardous waste on-site for 90 days without a permit provided that the generator complies with the requirements in articles 3 and 4 of chapter 15 and section 66265.16.

Title 22 §66265.31 (Article 3) states that facilities shall be maintained and operated to minimize the possibility of any unplanned sudden or non-sudden release of hazardous waste which could threaten human health or the environment.

The bermed area beneath the grate in the stripping room was filled with a D002 hazardous waste.

Title 22 §66265.34(a) (Article 3) states

Storage over 90 days

Title 22 §66262.34(a) (40 CFR §262.34(a))

Maintenance and operation of facility

Title 22 §66265.31 (40 CFR §265.31)

Waste Storage Area Internal Alarm

Title 22 §66265.34(a)

(40 CFR §265.34(a))

Lack of aisle space

CCR Title 22 §66265.35 (40 CFR §265.35)

Tanks

- Tank certification Title 22 §66265.191(a) (40 CFR §265.191(a))

- Tank inspections Title 22 §66265.195 (40 CFR §265.195) whenever hazardous waste is being poured, mixed, spread, or otherwise handled, all personnel involved in the operation must have immediate access to an internal alarm or emergency communication device.

There was no immediate access to an alarm or communication device in the Facility's waste storage area.

Title 22 §66265.35 (Article 3) states that the owner must maintain aisle space to allow unohstructed movement of personnel, fire protection equipment, spill control equipment, and decontamination equipment.

Approximately half of the drums in the waste storage yard lacked proper aisle space.

Title 22 §66262.34(a) states that a generator may accumulate hazardous waste on-site without a permit provided that the generator complies with the applicable requirements of article 10 of chapter 15. Title 22 §66265.191(a) (Article 10) states that the facility owner must keep on file at the facility a written assessment reviewed and certified hy an independent, qualified, professional engineer, that attests to the tank system's integrity.

The facility did not have this assessment performed by a qualified engineer for the 1200-gallon open tank of treated D002 sludge.

Title 22 §66265.195 (Article 10) states that the facility owner must inspect hazardous waste tanks daily.

Incomplete contingency plan

Title 22 §66265.52(e) (40 CFR §265.52(e))

open tank of treated D002 sludge on a daily basis.

Title 22 §66265.52(e) (Article 3) states that the contingency plan shall include a list of all emergency equipment, including each device's location and a brief description.

The facility's contingency plan lacked this information.

POTENTIAL NON-RCRA, CALIFORNIA-ONLY VIOLATIONS

Satellite Accumulation Area Labeling Requirements

Title 22 §66262.34(e)(1)(E)

A generator may accumulate as much as 55 gallons of hazardous waste at or near any point of generation if each container used for onsite accumulation is labeled with the words "Hazardous Waste" and with the following information:

- the initial date of waste accumulation is clearly marked and visible for inspection on each container used for accumulation of hazardous waste;
- composition and physical state of the waste;
- the particular hazardous properties of the waste;
- the name and address of the person producing the waste.

-Four 15-gallon carboys containing spent nickel filters (a non-RCRA, California only hazardous waste) by Line 5 were unlabeled;

 1 bucket of nickel-plated steel wool (a non-RCRA, California only hazardous waste) in the pumping room was unlabeled.

90-Day Storage Area Labeling Requirements

Requirements

Title 22 §66262.34(f)

Storage over 90 days

Title 22 §66262.34(a)

Open Containers

Title 22 §66265.173(a) (Article 9) (40 CFR §265.173(a))

Generators who accumulate hazardous waste on site without a permit shall comply with the following requirements:

- the date upon which each period of accumulation begins shall be clearly marked and visible for inspection on each container;
- each container shall be labeled or marked clearly with the words, "Hazardous Waste". Additionally, all containers shall be labeled with:
 - composition and physical state of the wastes;
 - statement which calls attention to the particular hazardous properties of the waste (e.g., flammable, reactive, etc.); - name and address of the person producing the waste.

89 55-gallon drums of non-RCRA hazardous waste were unlabeled in the Facility's 90 day storage area.

A (large quantity) generator may accumulate hazardous waste on-site for 90 days or less without a permit.

A minimum of 57 55-gallon drums of non-RCRA hazardous waste were stored in the Facility's hazardous waste storage area for over 90 days.

Title 22 §66262.34(a)(1)(A) states that a generator may accumulate hazardous waste on-site without a permit provided that the generator complies with the applicable requirements of articles 9 of chapter 15. Title 22 §66265.173(a) (Article 9) states that a container holding

hazardous waste must always be closed during storage, except when it is necessary to add or remove waste.

- Four 15-gallon carboys containing spent nickel filters (a non-RCRA, California only hazardous waste) by Line 5 were open
- One bucket of nickel-plated steel wool (a non-RCRA, California only hazardous waste) in the pumping room was open.

ATTACHMENTS

ATTACHMENT 1:

- Photos

ATTACHMENT 2:

- August 15, 1980 Notification of Hazardous Waste Activity

ATTACHMENT 3:

- November 15, 1999 Notification of Hazardous Waste Activity

ATTACHMENT 4:

- February 2, 2002 Santa Fe Springs Fire Department inspection report

ATTACHMENT 5:

- Map of Facility layout;

ATTACHMENT 6:

- December 2, 2003 3007(a) Request For Information letter from EPA to Facility

ATTACHMENT 7:

- December 22, 2003 response from the Facility

ATTACHMENT 1



Photo 1: Spent nickel filter cartridges, Line 5



Photo 2: Line 1 open, unlabeled bucket of black liquid



Photo 3: Line 1, open, unlabeled 5gallon bucket partially full of black liquid




Photo 4: Line 1, open, unlabeled carboy



Photo 5: Line 1: Two 30-gallon and one 10-gallon containers, open and unlabeled



Photo 6: Lines 1/3, open, unlabeled 55-gallon drum




Photo 7: Lines 1/3, two unlabeled 15-gallon carboys



Photo 8: Lines 1/3, open, unlabeled 55-gallon drum



Photo 9: Lines 1/3, three open, unlabeled 15-gallon containers



Photo 10: Lines 1/3, four 55-gallon drums, labeled with 3/03 dates



Photo 11: Lines 1/3, two unlabeled 15-gallon carboys



Photo 12: Lines 2/4, unlabeled "tubes" filled with milky fluid



Photo 13: Lines 2/4, open 5-gallon bucket with "Hazardous Waste" label



Photo 14: Blasting booth with spilled blasting grit on floor



Photo 15: Line 3, assorted open, unlabeled containers



Photo 16: Line 3, open, unlabeled 15gallon container



Photo 17: Stripping drum storage area




Photo 18: Stripping area grating (corrosive liquid in area beneath)



Photo 19: Hazardous waste storage yard



Photo 20: Hazardous waste storage yard




Photo 21: Hazardous waste storage area



Photo 22: Unlabeled supersac of filter cake (F006)



Photo 23: 2300-gallon tank of spent cleaner solution




Photo 24: Spent cleaner solution tank label



Photo 25: Two 2500-gallon cadmium coagulate rinsewater holding tanks




Photo 26: 1-gallon container with sulfuric acid, labeled "Hazardous"

Attachment 1- Photos

从公司也在P·卡里·	FFIC	DEE ONLY
WCADO!	439	7911031
	100	13 16 11

	W CHUP 9	597911021
DESCRIPTION OF HAZARDOUS WASTES (contin	nued from front)	
AZARDOUS WASTES FROM NON-SPECIFIC SOURCES ste from non-specific sources your installation handles. U	Enter the four-digit number rom 40 CFR Part 261.31 f	or each listed hazardous
FOO1 FO	09	6:
		12
ZARDOUS WASTES FROM SPECIFIC SOURCES. Enter cific industrial sources your installation handles. Use addi	the four digit number from 40 CFR Part 281,32 for each	listed hazardous waste from
	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1.0
23 - 36 22 36 33 33 33 33 34 34 34 34 34 34 34 34 34	2 4 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	24
25 26		30
22 25 25 25	The state of the s	133 for each chemical sub-
P0 2 9 P0 9 9		
P0 3 0 P 1 0 4 3 0 9		41
P0 9 8 P1 0 6		AB: 17
STED INFECTIOUS WASTES, Enter the hour-digit num spitals, medical and research laboratories your installation	popular 17 and 18 page	ste from hospitals, veterinary
49		54 6 b.
ARACIENTICO COMPUSTO POR CAROLES	de una por expendence de sua chara	Derivate
ERESTO (6/As (6) Comp		100 B. Later Comp. L. Super-
ertify under penalty of law that I have personally ched documents, and that haved on my inquiry college that the submitted information is the passibility of the possibility of the poss		suomitted in this and all plaining the information, difficunt penalites for sub-
APURE M M	Darrell Golnick V.P.	8/15/80

Form 8700-12 (6-80) REVERSE



November 15, 1999

US EPA Region 9
Hazardous Waste Management Division
75 Hawthome Street, H-3-4
San Francisco, CA 94105

Please find following a Notification of Regulated Waste Activity form for Associated Plating Acquisition Corp. On November 15, 1999, Associated Plating located at 9636 Ann Street, Santa Fe Springs, California changed ownership. The new owner is Antonio Gracias. The operations will remain the same, as well as the on site contact person. The operator will now be Tim Grandcolas, Plant Manager.

If you have any questions, please call Domingo Garcia located at Associated Plating Acquisition Corp. (562) 946-5525 or Cindy Wilson at Electronic Plating Service, Inc. (310) 532-2345 x215.

Regards,

Cindy Wilson Safety & Environmental Manager

prov

48 No. 2050-0028 Expires 10/31/99 GSA No. 0246-EPA-OT

Please refer to Section V. Line-by-Line instructions for Completing EPA Form 6700-12 before completing this form. The information requested here is required by the (Section 3010 of the Resource Conservation and

Notification of Regulated Waste Activity

Date Received (For Official Use Only)

1100	ptalla	tion	s EP	A ID	Numb	oer (A	Hark '	X' in	the a	ppro	pria	te bo	(xi	1														
	A.	initi	al No	tifica	tion		X	. Sul	pesq				ion			c .	T	Ins	talla	tion'	3 EP	A ID	Nurr 7	ber 9	1	1	0	4
N	ame	of In	atell	ation	(incl	ıde c	omp	inv a	nd si	pecif	ic sit	te na	me)		>	U)	N.	U	U	7	3	U	7	9	1	T	U	
Δ	S	S	0	c	T /	Т	E	D		р	1	Α	Т	T	N	G		А	С	0	11	T	S		С	0	R	P
	Contraction of	MARINE.		tallat	ion (hvsl	70.02		s no	t P.C). Bo	x or	Rou	te Ni	ımb	-	>			4								i
	et		171		477						- , 1	at in the			0	P.	102	120	5	No.		45	-		l,u		641	TA
)	6	3	6	1	N	N		S	T	R	E	Ε	T						The state of the s									
_	et (C	_	nue	-	ally A			11-15				= 1			VIII)	120		1/2		SELS.		A STATE			No.	Nr.	d.	k
							T																					
ity	or T	OWIT				No.		or en		Sign	314	160	21		4	, F	Stat	Ð	Zip	Coc	le	5					1	
5	A	N	Т	A		F E		S	P	R	I	N	G	S			C	Α	9	0	6	7	0		2	9	9	5
ou	nty Co	ode	Co	unty	Name	9	mile.		1			, the		We see			. (4)	m.	7					1		120	re it	
			L	0	S	A	N	G	E	L	E	S														1.		
,	lnata	llati	on M	alling	Add	ress	(See	instr	uctic	nns)						-								ω.				
tr	et o	r P.C). Bo	X					on the	TO US	200	10		o per	$\epsilon_{\rm i}$		3			TEL ST	1.1			+ 10		district.		
	A	M	E									a IV es			- EH.	e il												
it	or 1	Town	T _C									Est.	- A				Sta	te	ZI	Co	de		i, i		2.54			
																								-				
1.	Insta	llati	on C	ontac	t (Pei	rson	to be	cont	acte	i reg	ardlı	ng w	aste	acth	ittle	at s	lte)		>		· · · · · ·							
les	no (l	.est)	,		FILE	41		4					1	(Fli	st)			0.4	7			1				(3)		
G	A	R	C	I	A									D	0	M	Ι	N	G	0					Carlot disease			
ol	THE	9	Jan Si	-13		, irr		4				15	3	-	one	Numl	ber (Area	Co	de a	nd N	The state of				1		
Q	A		M	A			-	R	-					5	6	2	-	9	4	6	-	5	5	2	5		100	9.
	Inst	-		Conta	Mary Nove o	Line Services				ons)								- 10 - Jr mi					200				- State 11	
P02.2	DOM: SHOW A P		Malli		B, SI	reet	or P.	D. Bo	×		510 c				10	de la					Ting.	1	6	T I		2/45	1	Ė
7	cution		100	1800		- 1			1				1											T Parks			<u> </u>	-
L	Х				also de	150-25	1 3/20	Testile.	8/66/8	- C/1		2 Ellip		7/5		100 No.	1000	Acres	TOTAL	n 12-	de	Mary Charles			V			
L			1			P. C.						1	-	7			Sta	te	Z	p Ca	de			Sept.	1	T		
Li li	y or	Tœw										2016					Sta	te	Z	p Ca	de	7.101.5		eres.				
The last	y or .	Tow lers!	nip (See tr	struc	tions	>										Sta	te	Z	p Co	de							
Till the Till	y or Own	Tow nersi	nip (itatio	istruc	tions	Owne		1 P. 10			310					Sta	ite	Z	p Co			one.					
THE THE A	y or Court	Town	hip (:	ilatio N	istruc n's Le	etions	Owne		A			A	s				Sta	ite		p Co								
THE THE A	y or Court	Town	hip (:	N or Re	istruc	etions gal (Owne	R		c			19. 4		T-			10.3		p Co			T	_				
	Y OF OWN	Town	nip (:	ilatio N	istruc	etions	Owne					-	19. 4	s	T	R	E	Ε				U		- T	I E		3	E
A A A	Court Name N Post, I	Town	insta 0 Box,	N or R	istruc	etions gal (Owne	R		c			19. 4	s	T	R		Ε		D Co	S			T	E		3	E

	167.35	ID - For Official U	se Only
VIII. Type of Regulated Waste Activity (Mark 'X' in the approp	riate boxes. Refer to In	structions)	
A. Hazardous Waste Activity		B. Used Oil Rec	cycling Activities
A. Greater than 1000kg/mo (2,200 lbs.) b. 100 to 1000 kg/mo (220-2,200 lbs.) c. Less than 100 kg/mo (220 lbs) c. Less than 100 kg/mo (220 lbs) c. Transporter (Indicate Mode in boxes 1-5 below) a. For own waste only b. For commercial purposes Mode of Transportation 1. Air 2. Raii 3. Highway 4. Weter 5. Other - specify Installation required instruction c. Less than 100 kg/mo (2,200 lbs.) c. Less than 100 kg/mo (220-2,200 lbs.) c. Less than 100 kg/mo (220	is Waste Fuel tor Marketing to Burne Marketers ind/or Industrial Furnace eiter Deferral all Quantity Exemption Type of Combustion ity Boller justrial Boller justrial Furnace jund Injection Control	a. Marketer Dire Oil to Off-Spe b. Marketer Who Used Oil Mee 2. Used Oil Burner of Combustion a. Utility Boiler b. Industrial Boil c. Industrial Fur 3. Used Oil Transp Type(s) of Com a. Transporter b. Transfer Faci 4. Used Oil Proces Indicate Type(s)	octs Shipment of Used octification Burner of First Claims the ts the Specifications r - Indicate Type(s) Device iller mace porter - Indicate bustion Device(s)
A. Characteristics of Nonlisted Hazardous Wastes. (Mar	Maria	sponding to the character	ristics of
(D001) (D002) (D003) Characteristic (D003) C	st specific EPA hazardous intaminari(s)) structions if you need to the property of the propert	o list more than 12 waste	
C. Other Wastes. (State or other wastes requiring a handler to	have an I.D. number;	See instructions.)	
2 2 1		5	6
X. Certification			
I certify under penalty of law that this document and all attachme a system designed to assure that qualified personnel properly ga person or persons who manage the system, or those persons dire is, to the best of my knowledge and belief, true, accurate, and con information, including the possibility of fine and imprisonment	ther and evaluate the in actly responsible for gat applete. I am aware that t	formation submitted. Bas pering the information, the	ed on my inquiry of the information submitted
Signature Name and O	ANDCOLAS PL	ANT MANAGER	11/15/99
XI. Comments			
Note: Mail completed form to the appropriate EPA Regional or 5	State Office. (See Section 1)		idresses.)



C., o anta Fe Springs Fire De, ar ...ent

Fire Protection Division Environmental Protection Division 11300 Greenstone Ave. Santa Fe Springs CA 90670-4619 (562) 944-9713 fax (562) 941-1817

Si	isiness Na te Address isiness Ov	9636 Ann. Ur	nit#
Da	te Inspect	ted 217 162 Inspector(s) Richard Kallman	
Due	popularice 3 Pate 3	Compliance 2nd Not addition	to comply by the ice will result in at legal ment action.
TEM	PROGRAM	DESCRIPTION	VIOLATION TYP
١.	HWG	Discontinue storage of wastes for longer than prescribed time frames (2200066262, 34(eXD.	W.NDT
7_	Ha6	Crucheroz 34(FD).	Miller
Э.	HOG.	ground (deteriorning/eaking drum, Diretal waste m ground, High pH material on ground/222cce 66265:31; CHSC 25189.5(2).	Class II
ч,	HOG	or removing materal (zxcce+6-265.173(a)).	lanor
S.	HWE	transpect storage meas weekly to Thered permit unit took tranks haily (recepibles. 174, colos. 195, colos. 34(d)2) - bole: Daily respective conducted, but monsistent with Findings humby inspection (i.e., materials leaked to gramal)	
0	HWP	Ensure personnel recome annual training (2200015265.16)	Winar
٦.	7.7.		1200 31 (X4)) Ca
8	7.7,	Submit notification form prior to treating washes (HESSER)	ob) Class H
The abor	SIGNATUI above condition ve violations by to our facility is no ation(s), please s	understand the above stated violations. After these violations have been corrected, I late fines. M. CHAS L. EVANS RE OF RESPONSIBLE PARTY PRINT NAME Is or practices represent a violation of the referenced code for which there are civil and/or criminal penaltic the specified due date may result in legal action being taken against the above parties. The giving of this not a representation by the City of Santa Fe Springs that no other violations exist on your premises. After the prove address.	DATE es. Failure to correct the tice and recent inspection r you have corrected the

SIGNATURE OF RESPONSIBLE PARTY

DATE

PRINT NAME

ASSOCIATED PLATING COMPANY

SITE MAP

9636 ANN STREET, SANTA FE SPRINGS, CA 90670 B D H A SORENSEN AVENUE LRC COIL COMPANY PROPERTY LINE (3) NNA LANDSCAPING AREA DAYTON O 3 **EMPLOYEE PARKING** SUPERIOR RESERVE PARKING LAB MSPS CONCRETE SUPPLY SHIPPING RECIEVING PLANNING/ CUSTOMER RESTROOM FENCE 119 LUNCH SERVICE PROPANE GAS TANK AREA BERNED AREA RACKING 183 PERCHLOROETHYLENE INSPECTION TANK AREA F Q.C. ROOM OFFICE VACANT LOT HMS LINE 5 BOND ROOM 142" (F) LINE 3 WASTEWATER STORAGE TANK LINE 1 (F) FUSING ROOM TER TREATMENT AREA 7 BATCH TREATMENT FILTER SLUDGE PRESS BOILER UNION OIL UNION OIL



UNITED STATES ENVIRONMENTAL PROTECTION AGENCY

REGION IX

75 Hawthome Street San Francisco, CA 94105-3901

July

Certified Mail No. 7001 0320 0002 4541 1288
Return Receipt Requested

DEC 0 2 2003

In Reply Refer to: Associated Plating Co. CAD043079110

Ms. Diana Crane Quality Manager Associated Plating Co. 9636 Ann St. Santa Fe Springs, CA 90670

Re: Request for Information Pursuant to 3007(a) of the Resource Conservation and Recovery Act


Dear Ms. Crane:

The purpose of this letter is to direct you or another duly authorized representative of the facility to respond in writing to this request for additional information concerning the hazardous waste inspection conducted at your facility by EPA and the Santa Fe Springs Fire Department inspectors on November 17, 2003.

Under the provisions of Section 3007(a) of the Resource Conservation and Recovery Act (RCRA), 42 U.S.C. 6927(a), the United States Environmental Protection Agency ("EPA") may require persons subject to RCRA to furnish information necessary for EPA to administer the Act. Pursuant to EPA's authority set forth in Section 3007(a), you are requested to submit the following information:

- In the print-outs you provided the inspectors, 186 containers of waste were identified. Please provide the following information regarding these containers:
 - the waste codes (RCRA and/or non-RCRA, California only) for the contents of each container;
 - the accumulation start date (i.e., when the container was first filled with the waste) with any available documentation, for each container.
- Please provide EPA copies of all hazardous waste manifests for the years 2001, 2002 and 2003;
- 3. Please provide EPA with copies of training records as described in Title 22 of the California Code of Regulations §66265.16(d)(1)-(4), that is:
 - the job title for each position at the facility related to hazardous waste management, and the name of the employee filling each job;
 - a written job description for each position listed;

- a written job description for each position listed;
- a written description of the type and amount of both introductory and continuing training that will be given to each person listed above;
- records that document that the training or job experience required have been completed.
- 4. Please conduct a hazardous waste determination, as required under Title 22 of the California Code of Regulations §66262.11, and provide EPA with the results (including waste code and accumulation start date (if hazardous)) for the following wastes:
 - Spent filters from the nickel baths;



 Oily liquid in open, 5-gallon green bucket and open, 5-gallon black bucket, by Line 1;



 Oily liquid in open, 5-gallon blue bucket, with label "electroless Ni solution", by Line 1;



 Yellow liquid in 2 30-gallon white open container and 1 10-gallon, white open container, by Line 1;




- Contents of unlabeled, black 55-gallon drum, by Line 1;



- Contents of unlabeled, white 55-gallon drum, by Line 1;




- Nickel filters in box, by Line 1;




- Contents of open, black 55-gallon drum, by Line 1;



- Contents of two unlabeled carboys, by Line 1;



- Contents of open, 55-gallon drum between Lines 1 and 3;



- Contents of 3 open, black containers between Lines 1 and 3;



 Contents of 4 55-gallon plastic drums, dated "3/03" and labeled "copper floor", between Lines 1 and 3;



 Contents of 2 open black 15-gallon containers and 1 open 5-gallon white bucket between Lines 1 and 3;



- Contents of open 5-gallon green bucket between Lines 1 and 3;




 Contents of 2 (1 open, 1 closed) white 5-gallon buckets, 1 black cylinder, 1 open blue 5-gallon bucket by Line 2;



- Contents of two open, unlabeled 5-gallon buckets (1 white, 1 red) by Line 2;



- Spent blasting media from sand blaster;



- Contents of open, 5-gallon white bucket in Maintenance Supplies Room;




 Contents of 2 white open 5-gallon buckets, 1 open 7-gallon red bucket, and one blue container by Line 3, north side;




- Contents of open blue container, north side of building;




- Contents of all 21 55-gallon drums in the outside stripping area;





Contents of white, open, polyurethane domed tank in waste storage yard (along with documentation of accumulation start date);



- Contents of 4 unmarked 55-gallon drums behind the polyurethane tank;



 Contents of one blue, open drum in front of decommissioned cadmium holding tanks;



- Contents of two holding tanks in outdoor storage area;




Contents of 12 unlabeled 55-gallon drums along south wall by facility's wastewater treatment plant;





- Contents of laboratory waste containers;





Section 3008 of RCRA, 42 U.S.C. 6928, authorizes the initiation of a civil enforcement proceeding for failure to respond fully to the information request set out in this letter. Section 3008 also authorizes criminal prosecution for knowingly making a false statement or omitting material information.

EPA regulations governing confidentiality of business information are set forth in 40 C.F.R. Part 2, Subpart B. For any portion of the information submitted which is entitled to confidential treatment, please assert a confidentiality claim in accordance with 40 C.F.R. 2.203(b). If EPA determines that the information so designated meets the criteria set forth in 40 C.F.R. 2.208, the information will be disclosed only to the extent, and by means of the procedures specified in 40 C.F.R. Part 2, Subpart B. EPA will construe the failure to furnish a confidentiality claim with your response with this letter as a waiver of that claim, and information may be made available to the public by EPA without further notice.

This request for information is not subject to review by the Office of Management and Budget ("OMB") under the Paperwork Reduction Act because it is not an "information collection request" within the meaning of 44 U.S.C. §§3502(3), 3507, 3512, and 3518(c)(1). See, also, 5 C.F.R. §§ 1320.3(c), 1320.4, and 1320.6(a). Furthermore, it is exempt from OMB review under the Paperwork Reduction Act because it is directed to fewer than ten persons. 44 U.S.C. §3502(4), (11); 5 C.F.R. §§ 1320.4 and 1320.6(a).

Your response to this request must be made by letter, signed by a duly authorized official, and submitted to EPA within twenty-one (21) calendar days from the date of receipt of this letter. Please address the submittal to:

Clint Seiter
Mailcode: WST-3
RCRA Enforcement Section
U.S. Environmental Protection Agency,
75 Hawthorne Street
San Francisco, CA 94105

If you have any questions regarding this matter, please contact Clint Seiter at (415)972-3298. Your cooperation in this matter is appreciated.

Sincerely,


Many Curill

Frances Schultz, Manager

RCRA Enforcement Office

cc: Steve Lavinger, DTSC

Richard Kallman, Santa Fe Springs Fire Department



December 22, 2003

Mr. Clint Seiter RCRA Enforcement Section U.S. Environmental Protection Agency 75 Hawthorne Street San Francisco, CA 94105

Mr. Seiter:

This letter is in response to the request for additional information concerning the hazardous waste inspection conducted at Associated Plating Company, 9636 Ann Street, Santa Fe Springs, CA 90670 on November 17, 2003. In response to the four items requested, the following is submitted:

- Printouts that were provided to the inspectors of the listing the 186 drums with the addition of the waste codes, if applicable, and the accumulation start dates. See attachment A.
- 2. Copies of all hazardous waste manifests for the years 2001, 2002, and 2003. See Attachment B.
- 3. The job title for each position related to hazardous waste management, the name of each employee filling each job, a written job description for each position listed, a written description of the type and amount of both introductory and continuing training that will be given to each person listed above, and records that document that the training or job experience required has been completed. See Attachment C.
 - (A) The job title for the position related to hazardous waste management is Waste Treatment Operator, and is listed as such on Associated Plating Company's census. The employees who perform this job function are Ken Hergesheimer and Gerardo Herrere.
 - (B) The job description to the Waste Treatment Operator is contained in Attachment C.
 - (C) The type and amount of both introductory and continuing training that will be given to each person filling the position is contained in the job description for the position. See Attachment C.
 - (D) Training records are contained in Attachment D.
- 4. The results of the hazardous waste determination for the materials depicted in the photographs provided. The waste codes, if applicable, and accumulation start dates, if the material is a hazardous waste, have been included. In addition, photographs taken by Associated Plating Company after the inspection have been used to further illustrate and document container contents. See Attachment D.

If you have any questions, comments, or need additional information, please feel free to contact me at (562) 946-5525.

Regards,

Diana F. Crane

Vice President of Quality

ana Din

cc: Richard Kallman, Santa Fe Springs Fire Department

COMPLETE THIS SECTION ON DELIVERY SENDER: COMPLETE THIS SECTION Received by (Please Print Clearly) B. Date of Delivery Complete items 1, 2, and 3. Also complete item 4 if Restricted Delivery is desired. ■ Print your name and address on the reverse so that we can return the card to you. ☐ Agent Attach this card to the back of the mailpiece, ☐ Addressee or on the front if space permits. 1. Article Addressed to: ☐ No If YES, enter delivery address below: Diana Crane 3. Service Type Certified Mall ☐ Express Mail ☐ Registered ☐ Return Receipt for Merchandise ☐ Insured Mail ☐ C.O.D. 4. Restricted Delivery? (Extra Fee) ☐ Yes 2. Article Number (Copy from service label) 7001 0320 0002 4540 8653 PS Form 3811, July 1999 Domestic Return Receipt 102595-00-M-0952

	U.S. Postal Service CERTIFIED MAIL RECEIPT (Domestic Mail Only; No Insurance Coverage Provided)								
8653	OFF	ICIAL	USÉ						
0454	Postage Certified Fee	s	Postmark						
0005	Return Receipt Fee (Endorsement Required) Restricted Delivery Fee (Endorsement Required)		Here						
0350	Total Postage & Fees Sent To	\$	0.						
7007	Street, Apt. No.; or PO Box No. 9636 Qun of 90570 City, State, 217+4 PS Form 3800, January 2001 See Reverse for Instructions								